

### **AUTO INSPECTION**

### **VEHICLE INFORMATION**

YEAR: 2004

MAKE: BMW

MODEL: 325xi

COLOR: Gray

VIN: WBAEU33484PR00000

Order Date: 03/23/2021

Inspection Date: 05/25/2021

Vehicle Location: Anchorage, AK

**Odometer:** 206,500 **Order ID:** 0000000



#### Comments

# **PHOTOS**

# Front



Front left side



Rear left side



Rear



Front right side



Rear right side



# Engine (hood open)



Dashboard (engine on)



Left Side Front Wheel and Rim (straight view - not angled)



Left Side Rear Wheel and Rim (straight view - not angled)




Trunk open/Truck Bed



**Odometer Reading (engine on)** 



Right Side Front Wheel and Rim (straight view - not angled)



Right Side Rear Wheel and Rim (straight view - not angled)



Photoinspection.com - Auto Inspection Page: 3/5

# Photo of Front Left Tire (Showing tread depth)




Photo of Rear Left Tire (Showing tread depth)





Photo of Rear Right Tire (Showing tread depth)





Front Seats (From passenger door)



### Rear Seats Roof Liner





**VIN Photo** 

